
TR/TPU
Add raw materials
Plasticizing anticipation
Pressurization stop
Injection
Pressure boost
Quick mold closing
location
Pressure maintaining
Mold opening
Fast turning
Slow turning
Cooling mold
Pulling head
Die opening cover
Taking products
Close mold cover